UNCLASSIFIED

AD NUMBER AD891222 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; 30 DEC 1971. Other requests shall be referred to Assistant Chief of Staff for Force Development [Army], Washington, DC 20310. **AUTHORITY** AGO ltr, 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DOD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE!
DISTRIBUTION UNLIMITED.



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310



DAAG-PAP-A (M) (6 Jan 72)

DAFD-OTT

18 January 1972

SUBJECT: Operational Reports - Lessons Learned, Hqs. 299th Engr Bn, 20th Engr Bde, 593 Engr Bn, 92d Engr Bn, Period Ending 30 Apr 1971 (U)

SEE DISTRIBUTION

33

l Section 2 of reports, subject as above, are forwarded for review and evaluation in accordance with para 4b, AR 525-15.

2. The information contained in these reports is provided to insure that lessons learned during current operations are used to the benefit of future operations and may be adapted for use in developing training material.

3. Information of actions initiated as a result of your evaluation should be forwarded to the Assistant Chief of Staff for Force Development, ATTN: DAFD-OTT, within 90 days of receipt of this letter.

4. As Section 1 of subject reports are not pertinent to the Lessons Learned program, they have been omitted.

BY REER OF THE SECRETARY OF THE ARMY:

DDC FILE COPY

4 Incl

1. DAFD-OTT 711226

2. DAFD-OTT 711047

3. DAFD-OTT 711161

4. DAFD-OTT 711100

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

US Army Materiel Command

Commandants

US Army Engineer School

US Army Signal School

VERNE L. BOWERS
Major General, USA
The Adjutant General

FEB 4 1972

magnatic .

Protective marking cancelled when separated from inclosure.

UNCLASSIFIED REPORT
DISTRIBUTION LIMITED TO U.S. GOV'T.AGENCIES.ONLY;
TEST AND EVALUATION; '27 Dec. 7; OTHER REQUEST
FOR THIS DOCUMENT MUST BE REFERRED TO THE ASSISTANT CHIEF OF STAFF FOR FORCE DEVELOPMENT (ARMY)
ATTN: FOR OT UT, WASHINGTON, D. C. 20310

FOR OFFICIAL USE ONLY

38.

Copies furnished: Office, Chief of Staff, US Army (DWSA) Deputy Chiefs of Staff Chief of Research and Development Assistant Chiefs of Staff Chief of Engineers The Provost Marshal General Commanders in Chief US Army, Europe **US Readiness Command** Commanding Generals US Army Alaska Commander, US Army Forces Southern Command Commandant of the Marine Corps Defense Documentation Center Commanding Officers US Army Construction Engineering Research Laboratory US Army Land Warfare Laboratory US Army Logistics Doctrine, Systems & Readiness Agency US Army Mobility Equipment Research & Development Center

ACRESS IM	hr .		
CESTI MILITE SESTION [KESTIMM []	
ODC DUEF NESTION		NESTING IZ	
BRYHOMMER			
MATTERCATION,			
N	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***********	
RY			
DISTRIBUTION/AVAILABILITY CODES			
BIST.	YAYAT 304	AL SECIAL	
	1	}	
12	1	1	
(1,1)	1		

EGCD-OP 30 April 1971
SUBJECT: Operational Report - Lessons Learned, 299th Engineer Battalion
(C), Period Ending 30 April 1971, RCS OSFOR 65 - (R3)

2. Lessons Learned: Commander's Observations, Evaluations, and Recommendations.

- a. Personnel:
- (1) Use of Hard Drugs
- (1) OBSERVATION: The foromost problem in the personnel area was the increase in the use of hard drugs. While not unique in this increase, the problems that crose were none the less relatively new to those in supervisory capacities. Corrective actions consumed a considerable amount of supervision and time.
- (b) EVALUATION: Due to the relative newness of the problem, most efforts by medical, legal, and military authorities failed to rectify the problems satisfactorily. Medical facilities for rehabilitation were scarce and the drug amnesty program was generally ineffective. Difficulties in obtaining substantial evidence with which to prosecute known drug users and the agonizing long period of time required to complete

DAFD-OTT 711226 Incl 1

EGCD_OP 30 April 1971 SUBJECT: Operational Report - Lossons Learned, 299th Engineer Battalion (C), Period Ending 30 April 1971, RCS CSFOR - 65 (R3)

administrative and disciplinary action were a constant source of poor morale among the men. In order to make every attempt to rehabilitate drug users, units were required to devote many hours in special supervision for their personnel. This factor often resulted in reduced effort for operational requirements.

- (c) RECOMENDATIONS: That modical facilities to treat drug users be dristically expanded and that administrative procedures for separation under AR 635-212 be streamlined and expedited at all cahelons of command.
 - (d) COMMAID ACTION: See (b) above.
 - b. Intelligence: None
 - c. Operations:
 - (1) Safety when working cranes
- (a) CBSERVATION: While working with cranes, the use of tag lines to guide a lead is a simple but often overlooked safety procedure.
- (b) EVALUATION: Tog lines should be used at all times when lifting and guiding a load with a crane. Often it is much quicker to avoid doing it and guiding the load by hand. This; however, is an extremely dangerous act and can result in serious accidents, some fatal.
- (c) RECOMMENDATION: Supervisors should insure that a few extra minutes are taken to attach a tag line to a load prior to lifting.
- (d) COMMAND ACTION: Safety Policy and SOP was revised to specifically require the use of tag lines when working with cranes.
 - (2) Maintonance of Equipment in Coastal Areas
- (a) OBSERVATION: Rust and corrosion of equipment occurs more frequently in a coastal area.
- (b) EVALUATION: As a result of the corrosive action of salt water and salt air in constal areas, equipment tends to rust and corrode more largerently. Increased frequency of washings and lubrications should be implemented to protect equipment in this environment.
- (c) RECOMMENDATION: Supervisors should insure that all equipment working in coastal areas be washed frequently (daily if possible) and lubrication be performed at other times beside normally scheduled services.
- (d) COMMAND ACTION: Fresh water washing facilities were provided for washing collected salt from vehicles. Wash intervals were changed to daily and lube intervals were changed to weekly.

2

EGCD_OP 30 April 1971 SUBJECT: Operational Report - Lessons Learned, 299th Engineer Battalion (C), Poriod Ending 30 April 1971, RCS CSFOR - 65 (R3)

(3) Expedient Winching Method for Extracting a Mired Dozer

- (a) OBSERVATION: D7E dozors with a winching capability can usually extract themselves when stuck if a sufficient deadman is available.
- (b) EVALUATION: A Scooploader can be used to dig an inclined plane into the earth with respect to the dexer and positioned in the hole to act as a deadman for the dezer from which to winch.
- (c) RECOMMENDATIONS: This method can be utilized successfully when other more direct methods fail.
- (d) GOMAND ACTION: This unit has adopted this procedure as an expedient method for freeing mired dozers.

(4) Construction of MSA1 Aircraft Revetments

- (a) OBSERVATION: Simplicity of construction has been a problem when building aircraft revoluents. It was found that by using #6 reinforcement bars and M8A1 matting that construction time would be cut in half.
- (b) EVALUATION: The use of these materials eliminated a great deal of welding time plus the necessity of driving pickets around the revetments. This method of construction also made it possible to move or dismentle the revetments at a later time. Design calls for removing the two outside piers of the male end of the MSA1 matting and insorting a U-shaped rebar cross-tie in the top hole of the one piece of matting and in the bottom hole of the corresponding opposite piece for dag a rigid X. The X braces are placed at each joint of matting while the remaining two pins are driven through to the female end of the adjoining piece of matting. End wills are constructed by placing matting on end in sufficient quantity to contain the fill. The revetment can be easily moved by lifting each end in turn with a crane until all fill material spills out the bottom, disassembling U-shaped X braces, transporting to new site where reassembly and fill operations take place. The revetments are creeted quickly and require little or no maintenance if the earth fill is primed with soil stabilizer after construction.
- (c) RECOMMENDATION: That this method be adopted as a highly effective expedient revetment and be included as an authorized design in the standard design construction plans for revetment construction.
- (d) GOMMAND ACTION: Prior to publishing of USAECV's standard design for helicopter revetments, the method of constructio described above was utilized. Requirements to comply with standard designs have prohibited us of the effective expedient method.

(5) Potholo Repair During Monsoon Worther

(a) OBSERVATION: While doing pothole repair, it was discovered that excessive amounts of water had percolated through the existing base course. This percolating effect had caused an upward pressure on the road surface

resulting in severe cracking and buckling of the road.

- (b) EVALUATION: Due to severe mensorn rains the percolating effect of the water was much greater than normal. An inspection of the designed section of the road revealed that had more attention initially been given to providing adequate drainage and a deeper base course, damage due to percolation could have been avoided.
- (c) RECOMMENDATION: In areas where heavy mensoon rains can be expected, reads should be constructed with a deeper than normal base course and adequate drainage structure should be provided.
- (d) CCMAND ACTION: Because this observation is primarily an after the fact discovery of an error made in initial read construction by another unit, command action is limited in scope. However, information has been discuinated to preclude the same error in future construction.

(6) Soil Stabilization Using Coment

- (a) OBSERVATION: Coment can be used as an effective expedient soil stabilizer in place of gravel.
- (b) EVALUATION: The use of cement to stabilize a soft sandy soil can save houling time. The coment is spread and mixed on the area which needs stabilizing and relicd with a sheepsfoot relier.
- (c) RECOMENDATION: That this nothed be used as an expedient method when time is short or hauling assets are limited.
- (d) COMMAND ACTION: This method of stabilization has been adopted by this unit for standard use, especially in sandy areas.

(7) Chinook Emplacement of Arch Culvert Sections

- (a) OBSERVATION: Chinooks may be used as a quick way to transport arch culvert sections to locations with limited accessibility. It has been observed that care should be exercised to avoid metal failure along the rim of the culvert where the elevises from the slings are placed through the bolt holes.
- (b) EVALUATION: An inspection should be nade to insure sufficient thickness is available where each clevis is attached through the bolt holes of the culvert. This metal thickness is critical with respect to the dynamic stress caused by weight displacement as the culvert is . lifted by the helicopter.
- (c) RECOMENDATION: Care should be exercised in lifting arch culverts using clovis attachments to insure at least a four point sling is utilized for sections greater than ten feet in length. This will

EGCD-OP 30 April 1971 SUBJECT: Operational Report - Lessons Learned, 299th Engineer Pattalion (C), Period Ending 30 April 1971, RCS CSFOR - 65 (R3)

sufficiently reduce the dynamic stress at each attachment.

- (d) COMMAND ACTION: A four point sling is utilized by this command when transporting arch culverts by Chinook.
 - d. Organization:
 - (1) Operations Section for Combat Engineer Company
- (a) OBSERVITION: MTOE 5-37GP501 does not make provisions for an operations section in the Combat Engineer Company.
- (b) EVALUATION: The inordinately large Area of Operation's of the Battalien's line units necessitated their establishment of an operations section to control projects and equipment and to render reports. Units assigned a Sergeant E-5 and a clerk to handle all operational requirements. This section proved to be highly successful.
- (c) RECOMMENDATION: That the basic TOE 5-37G be modified to include an Operations Sergeant and one clerk to handle operational requirements.
 - (d) COMMAND ACTION: See (b) above.
 - e. Training:
 - (1) ARVN Training:
- (a) OBSERVATION: U.S. operators should be cognizent of the importance of training ARVN operators.
- (b) EVALUATIONS: Any operator assigned to a vehicle in which an ARVN soldier is training should have the importance of this operation stressed to him. The ARVN, who was paired with a U. S. operator that was interested in the training, graduated at such higher proficiency level.
- (c) RECOMMENDATION: Stress the importance of ARVN Training to operators and supervisors.
- (d) COMMAND ACTION: This battalion uses only highly notivated personnel to train ARVN personnel.
 - f. Logistics:
 - (1) Stockpiling of Bridge Parts for Forgency Bridge Repair
- (a) OBSERVATION: Effective emergency bridge repair requires that the correct amount of bridging components be quickly located and located. Often locating and locating of bridge components is done at night and



8

SUBJECT: Operational Report - Lessons Learned, 299th Engineer Battelion (C), Period Ending 30 April 1971, RCS CSFOR - 65 (R3)

confusion results as to numbers and types of components to be leaded.

- (b) EVALUATION: A system of stockpiling bridge parts so as to relieve the work of ascertaining numbers of each type component necessary to complete a certain size bridge, would save time and mistakes. Such a system would be to stockpile the bridge by bays. All parts necessary to complete one bay would be placed in one stockpile. Personnel responsible for leading would then morely have to know how many bays to lead and lead that number of stockpiles plus erection equipment. Sandbags can be utilized to store sufficient numbers of small parts (pins, clips, etc).
- (c) RECOMMENDATION: That units responsible for emergency bridge repair consider stockpiling bridge components in a manner such as one suggested above.
- (d) COMMAND ACTION: Bridge assets of the battalion are stored in the above detailed manner.
 - g. Communications:
 - (1) Redio Repeir Perts
- (a) CBSERVATIONS: The practice of using substitute repair radio parts and local fabrications in the face of critical shortages of authorized spare parts can decrease equipment operational deadline totals.
- (b) EVALUATION: The temporary use of an interchangeable repair parts (i.e. tubes, relays, modules, etc.) can often restore a significant portion of deadlined radio equipment to an operational condition. Prior to accomplishing the substitution, careful investigation must be made of the specifications of the equipment so as to not damage internal mechanisms of the equipment.
- (c) RECOMMENDATION: That this practice be used only for emergency requirements.
- (d) COMMAD ACTION: Procedure instituted to insure that when a critical radio shortage exists, all non-operational radios are channeled through the battelion communications section to provide Assets for controlled substitution prior to evacuation to direct support maintenance.
 - (2) Maintenance of Radio Antonnais
 - (a) OBSERVATION: Joints on radio antennas are freezing up.
- (b) EVALUATION: Due to the higher hundrity and corrosive properties of the air in a tropical climate, joints on vehicle radio antennes tend to corrode, and freeze, rendering them impossible to separate and results in damaged equipment.

FOR OFFICIAL USE ONLY

TOT REPRODUCIBLE

EGCD_OP 30 April 1971 SUBJECT: Operational Report - Lessons Le mod, 299th Engineer Bettelien (C), Period Ending 30 April 1971, RCS OSFOR - 65 (R3)

- (c) RECOMMEDATION: That each joint be separated and clonned weekly,
- (d) COMMIND ACTION: This procedure for maintenance of entennas has been integrated into the weekly maintenance day programs.
 - (3) Heat Protection for Redio Sots
 - (a) OBSERVATION: Soveral radios have failed due to overheating.
- (b) EVALUATION: Radios should be shielded from the direct rays of the sun and sited to insure free circulation of air around the sets whenever possible.
- (a) RECOMMEDATION: Redio sets which full in operation should be allowed to cool several hours, and then be tested again for satisfactory operation prior to evacuation to a higher scholon of repair.
 - (d) COMMAND ACTION: Procedure in parc. (c) has been adopted.
 - (4) Field Expedient Use of i,T-292
- (a) OBSERVATIOF: ΔT -292 antonnas often have to be not up for a short time at a rôley site.
- (b) EVALUATION: By using loss than seven most sections and by driving the most stake just under the front bumper of a vehicle, the most can be supported without the use of guy wires. Slip the most through the lifting shackle on the front bumper and ento the most stake. This procedure works very satisfactorily in winds up to 20 MPM.
- (c) RECOMMENDATION: That this procedure be utilized for short period use of AT-292.
 - (d) CCRAND ACTION: Procedure adopted as stated.
 - h. Matorial: Hono

i. Other: dene

JIM B. LIM LTC, CE

cartiding.

NOT REPRODUCIBLE

BCEGA-C (30 April 1971) 1st Ind SUBJECT: Operational Report-Lessons Learned of the 299th Engineer Battalion (CBT) Period Ending 30 April 1971, Ros CSFCR-65 (R3)

Da, Headquarters 35th Engineer Group (Const) APO 96312, 9 June 1971

TO: Commanding General, United States Army Engineer Command, Vietnam ATTn: AVCC-ലO APO 90491

This headquarters has reviewed the Operational eport-Lessons..Learned for the period ending, 30 April 1971 from the 299th Engineer Battalion (JBT) and concurs with the comments and observations of the Commander.

FOR THE COMMINDER:

11

RICHARD A. PALM

CPT,CE

Adjutant

AVUC-NO (30 Apr 71) 2nd Ind
5UbJECF: Operational Report - Lessons Learned, 299th Engineer battalion
(Combat), reviod Ending 30 April 1971, RCS USFOR - 65 (R3).

niu Uz army Engineer Command Vietnam, ArO 90491 15 JUN 1971

TU: Commanding General, US army Vietnam, aTTN: aVhDO-DO, AtO 90375

- 1. The significant activities and lessons learned have been reviewed and are an adequate reflection of the units operation during this period.
- 2. Reference item concerning "bafety with Cranes", page 7, parabraph lc (1). Concur. Additionally proper maintenance and storage of these lines will be stressed within this neadquarters. No action by USARFAC or DA is recommended.
- J. Reference item concerning "Expedient Winching Methods for Extracting Fired Dozers", page 8, paragraph 2c (j). Recommend this recedure be used only in emergency situations. An effective log deadman could be installed in the same comparative time as this procedure, and the possibility of damaging a scooploader would be avoided. No action by USARFAC or DA is recommended.
- 4. Reference item concerning "Construction of MbAl Aircraft Revetments", page c, paragraph 2c (4). The design is an acceptable expedient design although it should be noted that the minimum width should be four feet and the maximum neight limited to three sections of mbAl steel mat (about five feet). The width and neight limitation are necessary for stability since the revetment merely rests on the ground. The major misadvantage of this design are the height limitations and large amount of fill required. No action by UlandaC or DA is recommended.
- 5. Reference item concerning "Operations Section for Combat Engineer Company", page 10, paragraph 2d (1). Nonconcur. The recommendation that the basic TCE 5-37G be modified to include an Operations Sergeant and one clerk to handle operational requirements is considered to be invalid for all units organized under this TOE. It is true that an Operations Sergeant is not provided in the TOE. The TOE of a Compant Engineer Company does authorize three administrative type enlisted personnel, an E-8 First Sergeant and two clerks, one E-5 and one E-4, in addition to an Executive Orficer. Under normal conditions these personnel would carry out the duties of an operations section under the guidance of the Company Commander. If abnormal circumstances prevail, as they apparently did in this unit's case with a large area of responsibility, and the Company Commander desires an operations section, one may be formed from assets within the subordinate platoons of the unit.
- o. Reference item concerning "ARVN Training", page 10, paragraph J. Concur with comments. Item can be included in weekly Command Information. A one nour class added to replacement training in July 70 covers "Why Vietnam" and our role as pertains to Vietnamization. No action by UDARFAC or DA is recommended.

AVCC-MO

SUBJECT: Operational Report - Lessons Learned, 299th Engineer battalion (Combat), Period Ending 30 April 1971, RCS CUFOR - 05 (R3).

- 7. Reference item concerning "Radio Repair Parts", page 10, paragraph 2g (1). Concur, providing extreme care is taken in insuring that substitute items are positively identified by qualified personnel to be an acceptable substitute item. Substitution of a mismatching part could cause damage of a much more serious nature than originally encountered. No action by USARFAC or DA is recommended.
- 8. Reference item concerning "Maintenance of Radio Antennas", page 11, paragraph 2g (2). Concur. Cleaning of radio antennas is a normal weekly preventative maintenance procedure (see appropriate TM). In conditions of exposure to extreme heat, humidity, rain and dirt, antennas (and the radios themselves) should be cleaned much more frequently. No action by USARPAC or DA is recommended.
- 9. Reference item concerning "Field Expedient use of AT-292", (KC-292) page 11 paragraph 2g (4). Concur. Using personnel should understand, however, and be willing to accept, a somewhat reduced range of the radios concerned. This is due to increased propagation loss caused by reducing the elevation of the antenna above the ground. No action by USAHPAC or DA is recommended.

FOR THE COMMANDER:

CHARLES M. PETERSON

1LT. CE

Act Asst Adjutant General

14

AVHDO-DO (30 Apr 71) 3rd Ind CUBJECT: Operational Report-Lessons Learned, 299th Engineer Battalion (C), Period Ending 30 April 1971, RCS CSFOR-65 (R3)

Headquarters, United States Army Vietnam, APO San Francisco 96375 1 0 AUG 1971

TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-FD APO 96558

This Headquarters has reviewed the Operational Peport-Lessons Learned for the period ending 30 April 1971 from Headquarters, 299th Engineer Battalion and concurs with comments of indorsing headquarters.

TOR THE COMMIDER:

CPT AGC ASSISTANT A JULIANT GENERAL GPOP-FD (30 Apr 71) 4th Ind

SUBJECT:

Operational Report-Lessons Learned, 299th Engineer Battalion (C), Period Ending 30 April 1971,

RCS CSFOR-65 (R3)

1 7 SEP 1971

HQ, US Army, Pacific, APO San Francisco 96558

HQ DA (DAFD-ZA), WASH DC 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

Mr. L. Mr. ah

M. L. NAH

llt, AGC

Asst AG

AVBI-OS

SUBJECT: Operational Report - Lessons Learned of Headquarters, 20th Engineer Brigade for Period 1 November 1970 - 15 April 1971, RCS_CSFOR-65(RZ)

SECTION II - LESSONS LEARNED

- 1. Command None.
- 2. Personnel and Administration
 - a. Assistance-in-kind (AIK) Funds and Daily Hire Local Nationals(DHLN).

OBSERVATION: On several occasions (primarily in the 34th Engineer Group) mission accomplishment was hampered because the AIK allocation was in danger of being overdrawn or the AIK Fund Custodian was required to travel to Long Binh to draw additional funds.

EVALUATION: Daily Hire Local Nationals are an extremely valuable and economic source of manpower. In each Engineer Group there are numerous projects which, for economic reasons alone, dictate maximum utilization of DHLN personnel.

RECOMMENDATION: That the AIK Fund Program be modified to provide for:

- (1) Simplification of the administrative processes which would allow the using commander to deal directly with the approval authority.
 - (2) Authorize a "Class B Agedt" at battalion level.
 - (3) Allow for a higher Imprest Fund ceiling.
 - b. Local National Direct Hire (LNDH).

OBSERVATION: As engineer troop strengths are drawn down with

DAFD-OTT 711047 Incl 2

FOR OFFICIAL USE ONLY

16



18

AVBI-OS

25 April 1971

SUBJECT: Operational Report - Lessons Learned of Headquarters, 20th, Engineer Brigade for Period 1 November 1970 - 15 April 1971, RCS CSFOR-65(RZ)

continuing unit redeployments, the shortage of US manpower has affected our capability to accomplish some missions.

EVALUATION: To offset the loss of troop strength the use of LNDH has been found effective. This manpower source costs less than one-fifth as much as US Troop labor, it provides a continuity not available with the short tour turn around of US troops, and it fosters the nation building concept by teaching technical skills.

RECOMMENDATION: Maximum possible use of LNDH should be made for the reasons stated above. Every mission should be approached with the consideration of utilizing LNDH. Where possible (e.g. a Type B Construction Battalion) US troop spaces should be eliminated and replaced with LNDH on a permanent basis.

3. Operational Support Section - Standard Firebase Design

OBSERVATION: In building firebases, construction of heavy gun platforms varied according to the constructing unit, the customers and the

EVALUATION: A standard heavy gun pad design for the brigade did not exist.

ACTION TAKEN: A heavy gun pad was designed for all-weather conditions and approved by 23d Arty Gp. This is now the IIFFV (TRAC) Standard design for heavy gun pads. Its first application was at FSB Lanyard II.

4. Construction Operations Section

a. LOC Construction Sequence

OBSERVATION: In LOC construction a great deal of effort has been expended in completing the shoulders that were omitted or poorly done during initial construction. This has resulted in inordinate effort required to complete LOC routes to the point where they can be transferred to GVN.

EVALUATION: The reason the failure to construct shoulders initially from a natural emphasis to get as much road surfaced as possible to serve the tactical units and the economy. More "miles paved" could be realized by deferring shoulder and drainage work and concentrating on the limits of the travelled way.

AVBI-OS

SUBJECT: Operational Report - Lessons Learned of Headquarters, 20th Engineer Brigade for Period 1 November 1970 - 15 April 1971, RCS CSFOR-65(RZ)

RECOMMENDATION: Concentration on only the "miles paved" causes an increase in the overall effort to complete the road to meet turnover criteria. The complete road should be constructed in an orderly sequence to include shoulders and drainage and short increments (5 - 10 Km) should be inspected and transferred to the GVN as they are completed.

b. Quality Control

OBSERVATION: Quality control, especially in LOC construction, has been one of the biggest problems. The specifications for LOC construction were generally known at the higher command and staff levels, but the working supervisors (Company grades and NCO's) demonstrated limited knowledge.

EVALUATION: In developing a program to improve quality control, the reasons for poor quality control were defined as either lack of knowledge of proper specifications, lack of knowledge of techniques to most specifications, or indifference.

RECOMMENDATION: In order to correct the lack of knowledge standard specifications must be published and must be read. Glasses must be conducted down at the field supervisory level to explain specifications and technique. A very successful program was initiated to put condensed specifications for specific types of work (i.e. paving, patching, DRST, etc) on a 3 x 5 card and require field supervisors to carry them at all times. This greatly reduced the "lack of knowledge" problems and the professional product resulting from improved quality control fostered a sense of pride that eliminated much of the indifference that had been noted.

- 5. Intelligence None.
- 6. Communications None.
- 7. Safety None.
- 8. Logistics MRE System

OBSERVATION: The depot supply system has difficulties in providing timely, dependable response to unit requisitions. Requisitions are submitted and disappear with no status provided, releases are unpredictable and slow or erratic in being returned, depot inventories are inaccurate and false material shortages or averages are depicted and routine handling of release documents adds several days or weeks to actual pickup of materials.

3

18

ن0--الذلاية

25 April 1971

HOT REPRODUCIBLE

Subject: Open tional Report - Lessons Learned of Headquarters, 20th ingineer Brig de for Period 1 November 1970 - 15 April 1971, Nos Cural-65(kg)

EVALUATION: UCAICOV and USADLEN analyze these problems as the result of poor depot locations records, required inventor, adjustments and past misuse of the supply system. Steps of being taken to improve depot service but in the interim units have had to provide on-the-spot expeditors to coordin t. with ICCV commodity managers, search depot assets, hand carry recuisitions when permitted, and hend corry high priority releases for werehous spickup.

RECOMBIDATION: All units should continue to provide high quality expeditor: who know the ICCV and depot systems in order to insure timely response to supply requirements. The neterial Readiness Expeditor (ME) is: critical link in the units supply capability and must set the part of in S-4 forward in the vicinity of the depot.

y. Mintenance - Drill Expendebles

OBSERVATION: In the past, drill expendables have been procured through supply channels as supply items.

EVALUATION: Euch comfusion has grisen as to who should order these items, supply or maintanence. There is often trouble determining whother or not a drill expendable is a repair part or a supply item. Also, repair part chann is often respond nore quickly to filling requisitions.

RECOMMENDATION: Suggest that all drill expendables be designated repair parts for easier identification and more expeditious procurement.

Colonul, CE

Deputy Commander

AVCC-MO (25 Apr 71) 1st Ind SUBJECT: Operation Report - Lessons Learned, 20th Engineer Brigade, Feriod Ending 15 April 1971, RCS CSFOR - 65 (R3)

114, US Army Engineer Command Vietnam, APO 96491 13 MAY 1071

9/

- TO: Commanding General, United States Army Vietnam, ATTN: AVHDO-DO, APO 96375
- 1. The significant activities and lessons learned have been reviewed and are an adequate reflection of the unit's operations during this period.
- 2. Reference Section II Lessons Learned, subparagraph d "Command Action". This paragraph was not added according to AR 525-15, dated 20 Nov 70. The 20th Engineer Brigade was inactivated 20 April 1971 and the above reference could not be added.
- 3. Reference item concerning "Assistance-in-kind (AIK) Funds and Daily Hire of local Nationals (DHLN)", page 13, paragraph 2a. Concur in part. Concur with recommendation (1) where the using commander may deal directly with the approving authority. This is currently in operation. The using commander may at any time call on the Programs and Budget Office, USAECV, which breaks out AIK daily hire funds for use by the Group commanders. Non-concur with recommendation (2) where a "Class B Agent" would be authorized at battalion level. A Class B Agent may only be located as low as a subordinate finance and accounting office. The AIK imprest fund custodian from the Group is the only individual who can deliver daily hire vouchers to the Class B Agent and exchange them for AIK funds. Concur with recommendation (3) to allow for a higher imprest fund ceiling. USARV Regulation 37-1, Appendix 1 requires that an imprest fund not exceed one-third of the quarterly authorization without prior approval of USARV and MACV. A request to increase the imprest fund as a percentage of the quarterly authorization that is properly substantiated should be sent to CG, USALCV, ATTN: AVCC-PB for indorsement to USARV and MACV. No action by USARPAC or Dn is recommended.
- 4. Meserence item concerning "Standard Firebase Design", page 14, paragraph 3. Concur. Standard design should be included in applicable FM's and TM's by appropriate Department of the Army Agencies.
- 5. Reference item concerning "LOC Construction Sequence", page 14, paragraph 4a. Concur. For nearly a year now, the emplasis has been placed on doing quality construction and completing all portions of small segments of road in a coordinated manner. The backlog of shoulder and drainage construction was created predominantly in prior years. The current emphasis on coordinated construction of complete roads is nost efficient on resources. It insures

AVCC-MO (25 April 1971) 1st lnd SUBJECT: Operation Report - Lessons Learned, 20th Engineer Brigade, Period Ending 15 April 1971, RCS CSFOR - 65 (R3)

that as rapidly as possible the subgrade is covered with base course, base course is surfaced, shoulders are constructed and surfaced, and drainage structures are completed. In this way, minimum sections of road are caught unprotected against rain, thus reducing the requirement to reconstruct damaged roads. No action by USARFAC or DA is recommended.

Concur. The staff of the Central Faterials Testing -aboratory has been increased so that close observation can be maintained over the quality control efforts of subordinate units. The quality Assurance School is attempting to train motivated technicians who will vigorously apply the concepts of quality control. No action by USARPAC or DA is recommended.

FOR THE COMMANDER:

CHARLES M. FETERSON

1LT. CF

Act Asst Adjutant General

AVHDO-DO (25 Apr 71) 2nd Ind

SUBJECT: Operational Report-Lessons Learned of Headquarters 20th Engineer Brigade for Period 1 November 1970 - 15 April 1971, BCS CSFOR-65 (R3)

Headquarters, United States Army Vietnam, APO San Francisco 96375

TO: Commander in Chief, United States Army Pacific, ATTH: GPOF-FD APO 96558

This Headquarters has reviewed the Operational Report-Lessons bearned for the period ending 15 April 1971 from Headquarters, 20th Engineer Britade and concurs with comments of indorsing headquarters except as indicated helew:

- a. Peference item concerning "Assistance-in-kind (ATM) Funds and Dmily Fire Local Nationals (DNEM)," nage 13, paragraph 2a and late Indorsement, paragraph 3: Nonconcur. Funds expended now for Baily Fire employees are based on an hourly salary with the maximum wase at .30.VIC per hour and no additional benefits. Some units use as many as 15 to 170 Paily Mire employees per day, however, to convert these type employees to Q'MA funded nositions the following must be considered:
 - (1) Faily Hires are not required to have MS clearences.
- (2) Paily Rires do not receive any other benefits, i.e., sick leave, annual leave, Tet honus, separation allowances, death allowances, etc. The cost to the US forces if the conversion was authorized would be astronomical and security requirements questionable, plus to make direct hires they would undoubtedly be given higher hourly may along with benefits.
- (3) The unit should request an MTDA change, with substantiation of the needs and requirements for the additional spaces but not be authorized a blanket authority to employ Direct Hires in lieu of Daily Fires. Unit has been so advised.
- b. Feference item concerning "Maintenance Drill Expendables," page 16, paragraph 9: Nonconcur. Requisitions for drill expendables are handled in the same manner whether processed as a supply item or a repair part. In the case of a supply item, the requisition is processed by a supply DSM. If the drill expendables are processed as remain parts, a maintenance DSM processes the requisition. The difference in procurement is due to varying response by the DSM involved.

AVERO-PO (25 Apr 71) 2nd Ind SUMECT: Operational Report-Lessons Learned of Headquarters 20th Engineer Brigade for Period 1 November 1970 - 15 April 1971, BCG CSPOR-65 (P3)

The Arry Master Data File held by the DSU's indicates category of aunuly that drill expendables fall under. Unit has been so advised.

FOR THE COMMANDER:

1. L. CHILDRESS

CPT AGC

ASSISTANT ADJUTANT GENERAL

25

GFOP-FD (25 Apr 71) 3d Ind SUBJECT: Operational Report-Lessons Learned, HQ 20th Engineer Brigade, Period Ending 15 April 1971, RCS CSFOR-65 (R3)

HQ, US Army, Pacific, APO San Francisco 96558 14 SEP 1971

TO: HQ DA (DAFD-ZA), WASH DC 20310

This headquarters concurs with subject ORLL as indorsed with the following comment:

Reference paragraph 3, Section II, page 14: Subject design was accepted as the standard for II Field Forces, Vietnam. The 1st Indorsement by U.S. Army Engineer Command Vietnam recommended in paragraph 4 that a standard design be included in applicable FM's and TM's by appropriate Department of the Army agencies. The design resembles Figure 2-28, FM 5-15, Field Fortifications, dated August 1968, but uses a rectangular sleeper pattern (vice radial) and 4" planking (vice 2"). Recommend that the report and the design be forwarded for review by the proponent agency for this manual (Commandant, U.S. Army Engineer School, Fort Belvoir, Virginia, 22060).

FOR THE COMMANDER IN CHIEF:

M. L. MAH llt, AGC Asst AG

2. Leasen Learned: Commanders Observations, Evaluations and Recommendations:

- a. Paracapal None
- b. Intelligence None

c. Operations

57

- 1) Proper Cleaning of Vehicles.
- unit, and the level of standards for appearance and maintenance requires all vehicles to be clean and clear of mud and dust.
- b) EVALUATION: It was found that by constructing a "Y" made of one inch pipe with the proper compressor hose fittings welded to the two pipes on the top of the "Y", and a 3 inch reducer placed on the remaining end, that this requirement could be not very quickly and with a much higher level of efficiency. It is necessary to have a compressor of at least 60 cfm capacity and a water hose facility capable of being utilized with an air compressor hose. The "Y" receives compressed air and water at the same time which produces a much stronger force that theroughly cleans all surfaces.
- c) RECLIMINDATIONS: Although this system may already have been discovered by other units, the following is important information which may not be clearly understood by units utilizing this cleaning device. Insure that all using personnel clearly understand that they must shut the water source off first and approximately one minute later, they can turn the ecupressor off. If the sequence is reversed, the water will feed back through the air compressor itself. Although this does not seriously injure the internal parts of the compressor, it does induce unnecessary work to clear the compressor of the water prior to operating the equipment again. This is especially important in freezing weather as reversing the shut down procedures mentioned will seriously damage the compressor during weather that falls below the freezing point of water.

d. Organization None

e. Training

- 1) Experienced Crane Operators.
- g) OBSERVATION: The type of mission requirement that the 93d Engineer Company (FB) receives in conjunction with the

25

DAFD-OTT 711161 Incl 3 equipment authorized has created a serious problem in the area of experienced crane operators. The amount of training on class 60 bridges 'each crane operator within the 7th Engineer Brigade has received varies from none at all to these few ; fully trained operators. This lack of experience seriously; hinders the construction of the class 60 bridge for both unit training missions and more seriously fer company training and ORT's of the various units that the %3d Engineer Company (FB) supports:

- b) EVALUATION: Bue to the limitation of only one crane under the METOE for this unit and the fact that at least two or more construction sites are required at all bridging sites when units train, the 93d Engineer Company (FB) cannot provide the experienced operators as required. The most critical construction phase is the installation of the ramp section which would normally take twenty minutes per shore with an experienced operator, and as much as forty-five minutes with an inexperienced operator. The overall safety profile is lowered when crane operators are utilized without any previous experience.
- c) RECOMMENDATIONS: That all crame operators within each of the support battalions of the 7th Engineer Brigade be evaluated to determine their capabilities when working with class 60 bridging. If the individual operators involved in this evaluation fail to meet the accepted standards of operation, each man should receive an CJT period at garrison station to become familiar with the pecularities of the class 60 bridge.

An additional recommendation is to insure that no unit within the 7th Engineer Brigade request company testing for class 60 bridging when it is necessary to provide the use of their organic cranes if the operators have not experienced at least one mission working with the class 60 bridge. If it is necessary to violate this recommendation, then at least provide a block of four hours for the inexperienced crane operator to work with the bridge prior to utilizing him on the bridge site. This redommendation would not apply to units who request the use of class 60 bridging for training purposes. When a unit trains, everybody is learning. A Company or smaller unit tests and ORT's are not intended to train individuals but rather to test the individual's ability to respond and his ability to remember his training and use it.

d) CCMIAND ACTION: It is recommended that higher headquarters, to include VII Corps if necessary, apply whatever pressure is needed to insure that the current recommended changes to this unit's MATOE on crane authorizations be approved. This recommended change would authorize two cranes at level three.

f. Legistics

7.9

- 1) Field Maintenance Facilities.
- a) OBSERVATION: With the variety of training sites in USAREUR, ninety percent which contain no provision for a maintenance facility, and considering the number of maintenance problems which can develop when a unit is in the field, it was decided that the 93d Engineer Company (FB) needed some type of a maintenance facility that would provide inspection and a working space under all of the assigned vehicles utilized to provide the required bridge for support missions.
- b) EVALUATION: Since the construction of a pit would not only cause maneuver damages, but also requires an effort superior to the unit's organic ability, another solution was devised with acceptable results. The 93d Engineer Company (FB) is authorized and has on hand four complete sets of 135 class sixty bridge. Each set has a near and a far shore ramp section. In the history of the 93d Engineer Company (FB), as well as it can be traced, a mission requiring all eight ramp sections has never been levied on this unit.
- c) RECOMMENDATION: By carrying to the field one additional far shore ramp section and placing this section on a level ground area and heaving the center filler panel out, all organic vehicles could be inspected, serviced, and maintained with a higher morale developed by the troops and a more efficient job due to the "tread way pit" the ramp section simulated.
 - 2) Proper Utilization of all Vehicle Transfer Systems.
- a) OBSERVATION:: Instructions to all vehicle operators involved with the operation of a vehicle that has a transfer system (high and low) to not use the transfer gears while on open road operations will prevent many problems.
- b) EVALUATION: The most important factor here is the normal position of all transfer levers are such that while a piece of equipment is moving, an operator's position required to utilize the transfer case would prevent complete visual observation and thus prevent proper operation of the vehicle. The second area of consideration involves an experience factor on how to utilize the transfer system while in motion. Improper utilization of the transfer case would normally develop into some type of maintenance work on the vehicle which could have been prevented had the operator been experienced in the use of the transfer system.
- c) RECCMENDATION: The high transfer was intended for use on open roads as opposed to the low transfer for use on cross country traveling, not for speed shifting. Recommend that all operators be advised of this fact and strict speer-vision of the same be dinforced.

21

- 3) Smooth shifting of Vehicles During Cold Weather.
 Operations
- a) OBSERVATION: During cold weather operation of any vehicle the immediate use of different gears can be eased by utilizing the transfer case on those vehicles having a transfer case during the warm up time of the vehicle prior to movement.
- b) EVALUATION: By placing the transfer shift in neutral, then placing the gear shift in third gear, and releasing the clutch, the engine rpm is passed to the crankcase then to the gear housing. Because the lubricant that is used in the gear housing becomes very thick and sluggish during cold weather, shifting is very difficult in the early stages of vehicle operation unless the lubricant is brought to its normal operating viscosity.
- c) RECOMMENDATION: To insure smooth operation of all vehicles having a transfer case, operators should be instructed to utilize the neutral position for the transfer and place the gear shift in a medium speed. This causes the gears in the gearbox to revolve without moving the vehicle. This motion creates enough usage and heat in two or three minutes to insure smooth shifting from gear to gear in cold weather.

g. Communications

- 1) Control of Convoy Vehicles.
- a) CBSERVATION: When convoys in excess of three vehicles are necessary to move either equipment or personnel from point A to point B the use of all organic radio equipment has proven to be the most helpful factor in reducing vehicular accidents, control of all elements, and insure the arrival at the destination by the most direct route.
- b) EVALUATION: By placing any AN/PRC 25 radios available in vehicles at an interval of not more than four vehicles, and having vehicles with an AN/GRC 46's at the head and end of each 25 vehicle serial, a much tighter control can be ostablished and maintained.
- e) RECOMMENDATIONS: Recommend that all convoy precedure SOP's or directives include guidance to commanders to utilize all organic radios for convoy control. Radio contact throughout the convoy and each serial provides a more efficient means of recovering both disabled vehicles, vehicles that made a wrong turn, and notification to at least a part of the vehicles involved of a slow area, an accident, or an upcoming turn off the main route.

h. Material

- 1) Bailey Bridge Loading Plans,
- a) OBSERVATION: TM 5-277, dated August 1966, recommends that 2-80' double-single panel bridges be loaded so that the erection equipment is distributed over four 5 ton dusp trucks and one 22 ton pole trailer. The other 6 dump trucks transport panels, stringers, and chess. Panels, stringers, and chess are generally segregated on each truck.
- b) EVALUATION: This unit finds it more efficient to load one bay of double-single panel bridge plus two panels, on eight 5 tons per bridge plateon. Each plateon also has 5 tons to carry the launching nose, site layout, and tools and small parts and two 5 ton dumpatruoks each carrying two bays of ramp equipment. Transons and footwalk are each carried separately on 21 ton pole trailers.

The advantages of this loading plan are as follows:

- f) The number of trucks needed for any given bridge support mission can easily be determined simply by taking the corresponding number of bay loads plus the five miscellaneous loads that are needed regardless of length of bridge required.
- 2) Since each bay load carries all the parts for that bay (except bolts, clamps, pins, etc.) missing items can be more easily spected before leaving home station for the bridge site and policing up bridge at end of commitment.
- d) This bay load concept allows maximum amount of bridge to be unloaded by crane since each load is a stable bundle by itself. Stringers, chess, ribands, sway braces, buncing frames, and rakers need not be hand loaded into the dump bed. Two alings chable a crane to load and unload the materials quickly and mafely.
- 4) The loads are simple to stack even for inexperienced personnel, which saves loading time.
- 5) The site layout truck carries all the components which tends to prevent parts from being lost or misplaced. A canvas is placed on the vehicle to prevent the cribbing from becoming unduly wet and to prevent rollers from rusting.
- 6) One 5 ton is used as a tool and small parts truck which is equiped with a wood shed constructed with troop labor. Delicate equipment such as measuring tapes, string carpenters levels, wrenches, etc are kept locked up when not in use. This truck also carries safety pins, bracing frame bolts, rope, panel markers, hammers, etc. which tend to get lost if not tightly controlled. This truck also is used for the storage of other delicate or small items as needed.
- 7) This loading plan allows each plateon to marry 80 ft of double-single bridge with launching nose and combining both bridge plateons to meet the requirements of 130 ft of double-would with launching ness.

29

- C) Since all the bay loads and ramp loads are independent of each other the less of one load, or scentimes two, does not adversely effect the construction of the panel bridge.
- 2) RECOLUMNATION: That this bay loading plan be adopted either as a primary or alternate loading plan for panel bridge ocupanies.

1: Other

- 1) Bailey Bridge Site Layout Procedure.
- a) OBSERVATION: TH 8-277, dated August 1986, only resonmends one specific method of locating the sollers (rocking, plain, and construction)(in the site layout and that is with a template, most units do not have a template, therefore are left with no dependable site layout procedure.
- b) EVALUATION: As an alternate site layout method this unit suggests using 2 strings that run parallel to the center line string which would be used to locate the rollers both horizontally and vertically. Each string would be offset 7° 8" and parallel from the center line. After a roller has been placed on the highest point, the string on that roller should be leveled. Then two parallel strings allow the site Layout crew to easily determine the amount of digging and/or cribbing that is necessary. It also permits a final check on alignment of rollers before bridge construction.
- c) RECOMMENDATION: That this site layout procedure (see Figure #1) be adopted as an alternate method to the template system as suggested in TM-5-277.
- 2) Distance Perception Between Vehicles Traveling in Opposite Directions on Narrow Roads.
- a) OBSERVATION: All vehicles normally utilized in convoys by USAREUR units being CD, and with the variety of road widths in USAREUR together have caused problems when military vehicles pass each other.
- b) EVALUATION: It was decided by this unit that painting all west coast mirror assembly plates a striped yellow, could prevent part of the problem. Traveling at an angle of less than 5 degrees at a distance in excess of one hundred feet, the mirror ansembly is clearly visible. At an angle more than 5 degrees or a distance less than 100 feet, the mirror assembly blands with the remainder of the vehicle which is also CD in color and the distance that the mirror extends outward from the vehicle becomes difficult to estimate by an encoming driver. With the extension distance from the outer most part of the mirror assembly to the actual side of the vehicle extending twelve inches, a clearance distance of two feet between vehicles would involve a little destruction of mirror assemblies.

- e) RECOMMENDATION: Recommend that only the metal backing of the mirror itself need be painted, as this is the most extended part of the entire mirror assembly. One inch strips, yellow or white, at a forty-five degree angle to the sides of the mirror were found to suffice.
- 8. Mandewarters, Repartment of the Army Survey Information.

Companding

AETJEG-C (24 New 1971) 1st Ind JUNJUCT: Operational .o. ort - Lessons Learned, 563d Engineer.battalion, Feriod Ending 30 April 1971, RC3 CEFON-65 (F3)

DA, H., 7th Engineer Grigade, APO 09154

16 June 1971 .

TO: Commanding General, VII Corps, ATTH: AETUEN, APO 09107

This Readquarters has reviewed the basic report and concurs with all observations and recommendations with the following additions:

- a. Para 2e: This Headquarters concurs that float bridge units should be authorize a minimum of two cranes as the units can normally expect simultaneous employment at more than one bridging/refting site. The compatengineer pattalions (who normally assemble the bridge) lack sufficient cranes to adequately support multiple bridge/raft assembly sites. A recommended change to the MTO2 has seen sub-itted to the proponent unit.
- o. Pera 2f (1): The training sites normally used for bridge training ere field sites along rivers or at pands where no permanent or semi-parament facilities exist. This Headquarters concurs in the stated use of remp sections so long as mission support does not require their use.
- c. Pere 2h (1): The Headquarters concurs in the loading method and recommends it adoption Armwide. The bry load dus two panels described in pare 2h (1)(b) is carried on each of eight 5 ton trucks within each platoon.

cononial, or

NOT REPRODUCIBLE

UTSCC-0 (24 Pay 1971) 2d Ind

SUBJECT: Operational Report - Lessons Learned, 563d Engineer Battalion, Period Ending 30 April 1971, RCS-CSFOR-65 (R3).

DA, Headquarters, VII Corps, APO 0910? 16 JUL 1971

TO: Commander in Chief, United States Army Europe and Seventh Army, (ATTK: AEAGC-TU) APO 09403

This headquarters has reviewed the basic report and first indorsement and concurs with all observations and recommendations with the following additions and exceptions:

- a. Para 2e(1): Crane operator training discussed in this section is one that belongs to company level and would not have application outside the 563d Engr Bn. The responsibility for trained operators rests with the company commander who should initiate appropriate OJT programs as required.
- b. Para 2f(3): This headquarters does not concur with placing transfer shifts in neutral with transmission in third gear during warm-up periods in order to warm the lubricant as recommended in the basic report. The provisions of applicable vehicle technical manuals prescribe operating instructions during cold weather, and if followed will preclude shifting difficulties and damage to equipment power train assemblies. Placing the transmission in gear creates an additional load on a cold engine. Normal heat transfer from the engine to the neutral transmission is sufficient if warm-up time is as prescribed in the TM.
- c. Para 2g(1): This headquarters concurs with recommended use of radios for convoy control. Units utilizing this technique should coordinate moves out of normal areas of operation with their next higher headquarters to establish proper frequencies.
- d. Para 2i(2): This headquarters concurs with marking the back of rear view mirrors. It is further recommended that mirrors be marked with 3-M yellow or silver reflective adhesive tape which would allow for easy removal in event of hostilities.

FOR THE COMMANDER:

ALVA J. NESTER, JR JH

CPA, AGC

Asst AG

AEAGC-TU (24 May 71) 3d Ind

Operational Report-Lessons Learned, 563d Engineer Battalion, SUBJECT: Ending 30 April 1971, RCS CSFOR-65 (R3)

Headquarters, United States Army, Europe and Seventh Army, APO New York 7 AUG 1971

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. Forwarded in accordance with AR 535-15.
- 2. Recommendations found in paragraph 2h (1) and 2i (1) of basic correspondence are recommended for possible Army wide application.

FOR THE COMMANDER IN CHIEF:

WILLIAM D. MAPES

CPT, AGC Asst AG

SUBJECT: ORLL, 924 BEC, period onding 30 april 1971, RCS CSFOR - 65 (R3)

SECTION II, LESSONS LEARNED

- a. PHRSONMEL. None
- b. <u>HITHLIGHE</u>. Hono

NOT REPRODUCIBLE

- c. OPARATIONS.
 - (1) Expediting Construction
- (a) Observation. On a recent project, six concrete block buildings had to be constructed at least through roof level before the mensoons arrived. With the completed roofs on each building as a goal, the concrete block work upon which the roofing was dependent, had to begin as soon as possible.
- (b) Evaluation. A system of placing the perimeter footing for each building independently from the floor slab had to be developed in order for block work to eagin early.
- (c) Recommendation. Rather then pouring the perimeter footing and the building floor slab monolithically, the footing that would receive the loads of the block wall and roof could be poured before any work on the floor slat bugan. With this footing placed, the contentor block work could start. While the block was progressing toward roof level, the floor slab could be prepared and poured utilizing the walls for forming. Finally with all block completed, the desired roof could be constructed.
- (d) Cormand action. The advantages of an independent building footing were rewarding. The exterior block work, on a separate footing, began early and was accomplished concurrently with the underslab electrical and plumbing work, this meant that the slab would not delay the critical block work as long as had been originally thought. This approach was repeated throughout all the six buildings and resulted in all recling work being completed six weeks shead of schedule well before the rainy season.
 - (2) Placing Floor Slabs
- (a) Observation. By pouring an independent building perimeter footing and expediting concrete block placement, a problem of how to place the floor slabs quickly and with a minimum of manpower emerged.
- (b) Evaluation, Instead of placing concrete floor slabs in long, narrow rectangular strips ten to twenty feet wide, larger nearly square sections would be poured using a unique system of mobable screed pipes.
- (c) <u>Perconvendation</u>. Preparation of the slab area could be done with two distinct time and labor saving differences. The first difference is that there is no need for perimeter forms. The second difference the

DAFD-OTT 711100 Incl 4 FOR OFFICIAL USE ONLY

36

placement of small twelve inch sections of U-sh pad wickets. These pickets can be cut and shaped to receive two back salvanised pipe in ten foot grids at precisely the elevation required to position the screed sipe at finish floor level. With the picket supports so pieced, the two inch screed pipes can be positioned ton feet port, reducing the screed board length and saving the labor required to madle a larger twenty foot screed board, he the concrete gradually filled the sleb area and is screeded off in tenfoot increments, the two nowable acreed pipes orn be repositioned from one side to the other, Thus, the slab section could be poured in a nearly square configuration continuously with a minimum of effort, The finishing would proceed normally and when the slab section was complete.

- (d) Command Action. Recommendation was implemented and all buildings had high curlity floor slabs poured at a considerable saving over the conventional method.
- d. ORCANIZATION. None
- G. TRAINING. Hone
- COLTUNICATIONS. Wone

NOT REPRODUCIBLE

ELTERIAL.

- (1) Expediting of Construction Naterial.
- (a) Observation. Present supply procedures and direct support units do not provide for a supply system that is respondive to the needs of en engineer construction unit.
- (b) Evaluation. The problem has been partially solved by aggressive Unit and Group supply personnel. Techniques have been developed to obtain mapid requisition status and for locating supplies not listed as on-hand by the Dopot stock records.
- (c) Rucorymendation. Designated Group as a direct depot customer with direct support responsibility to its subordinate Battalions for equipment and construction material. Mission orientation and mission knowledge with supply authority would create a supply support responsive to the engineer unit's needs and mission.
 - (d) Generald Action. Recommendation is being given consideration.

. Zast burn

LTC, CE

Commanding

908_0P (20

DGB-OP (20 May 71) 1st Ind

SUBJECT: Operational Report-Lessons Learned, 92nd Engineer Battalion (Construction), Period Ending 30 April 1971, RCS CSFOR-65(R3)

DA, HQ, 159th Engineer Group, APO 96491

29 Nay 1971

THRU: Commanding General, USAECV, ATTN: AVCC-WO, APO 96491 Commanding General, USARV, ATTN: AVHDO, APO 96375 Commander-in-Chief, USARPAC, ATTN: GPOP-DT, APO 96588

TO: Assistant Chief of Staff for Force Development Department of the Army

Department of the Army Washington, D.C. 20310

- 1. The significant activities and lessons learned have been reviewed and are an acceptable description of the unit's operations this period.
- 2. Reference Lesson Learned "Expediting Construction," p 15, paragraph cl. Concur. Re-evaluation of construction sequences is often advisable due to nature of the Vietnam monsoons. This particular re-evaluation resulted in considerable savings in time and manpower. Application to similar modes of construction by DA is recommended.
- 3. Reference Lesson Learned "Placing Floor Slabs," p 15, paragraph c2. Concur. Application to similar modes of construction by DA is recommended.

FUR THE COMMANDER:

S. C. WATERS CPT, AGC Adjutant AVCC-NO (20May71) 2nd Ind

SUBJECT: Operational Report - Lessons Learned, 92 Engineer Battalion (Construction), Period Ending 30 April 1971, RCS CSFOR - 55 (R3)

HJ US Army Engineer Command Vietnam, AFO 96491

1 JUN 1971

TO: Commanding General, US Army Vietnam, ATTN: AVHDQ-DO AFO 96375

- 1. The significant activities and lessons learned have been reviewed and are an adequate reflection of the unit's operation during this period.
- 2. Reference item concerning "Placing Floor Slabs", page 15, paragraph c(2). Concur. This should be reviewed by the appropriate Engineer School Department to insure it is adequately covered in current manuals and class instructions.

FOR THE COHMANDER:

CHARLES M. PETERSON

llt, ce

Act Asst Adjutant General

Charles m Peterson

43

AVHDO-DO (20 May 71) 3rd Ind 2 9 SEP 1371
SUBJECT: Operational Report-Lessons Learned, 92d Engineer Battalion
(Construction', period ending 30 April 1971, RCS CSFOR - 65 (R3)

Headquarters, United States Army Vietnam, APO San Francisco 96375

TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-FD, APO 96558

This Headquarters has reviewed the Operational Report-Lessons Learned for the period ending 30 April 1971 from Headquarters, 92d Engineer Battalion (Construction) and concurs with comments of indorsing headquarters.

FOR THE COMMANDER:

COL VCC

ASSISTANT ADJUTANT GENERAL

Cy furn: 92d Engr Bn USAECV

1/4/

GPOP-FD (20 May 71) 4th Ind SUBJECT: Operational Report-Lessons Learned, HQ 92d Engineer Battalion (Const), Period Ending 30 April 1971, RCS CSFOR-65 (R3)

HQ, US Army, Pacific, APO San Francisco 96558 | NOV 1971

TO: HQDA (DAFD-ZA), WASH DC 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

L.M. OZAKI CPT, AGC

ABSL AG

OHOLINGSTF LED	
Security Classification	
DOCUMENT CON	TROL DATA - R & D
ISSENTITY CIRCUITCALIEN OF ILLE AND ALL	amolation must be entered when the overall report to classified)
1 OHIGINATING ACTIVITY (Corporate author)	24. HEPORT SECURITY CLASSIFICATION
	FOUO
HQ, DAFD DA, Washington, D. C. 203	1) (2011)
, , , , , , , , , , , , , , , , , , , ,	10
and any see angle but retiod and	Learned, Hqs. 299th Engr Bn, 20th Engr ing 30 Apr 1971 (U)
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)	
Experiences of unit appared in company	nguraanay anamariaya
5. AUTHORISI (First name, middle initial, lest name)	suggency operations,
CG,20th Engr Bde, CO, 299th Engr Bn 593d	Engr Bn 92d Engr Bn
30 December 1971	74. TOTAL NO. OF PAGES 76. NO. OF REFS
SO DECEMBER 1971	
CONTRACT OR GRANT NO.	M. ORIGINATOR'S REPORT NUMBER(S)
A. PROJECT NO.	711226 711100
S. PROJECT NO.	711047
c. N/A	711161
	66. OTHER REPORT HO(5) (Any other numbers that may be seeigned this report)
d.	
10. DISTRIBUTION STATEMENT	
II. SUPPLEMENTARY HOTES	12. SPCHSORING MILITARY ACTIVITY
N/A	DAFD , DA, Washington, D. C. 20310
IJ. ABSTRACT	
•	
	!
	ı
•	

41

DD . FORM .. 1473

UNCLASSIFIED

Security Classification